



## PRODUCT INFORMATION BULLETIN

Date: January 24, 2014  
Number: 6957  
Division: Genie®  
Product Family: Residential Openers  
Product Series: Service Parts  
To: All Genie Professional Line Wholesalers, Dealers and Installers  
Re: Metal Drive Sprocket in the Belt T-Rails (for Models 1024/2024)

---

A new, enhanced drive sprocket was implemented into the production of belt rail assemblies. Changes can be seen in 8' rail shipments that left Baltic the week of December 16, 2013, and 7' rail shipments that left the week of January 6, 2014. The new drive sprocket assembly features an all steel design. The new service part number for the metal belt sprocket is 38416A.S.



New All Metal Sprocket



Current Plastic/Metal Sprocket

Additionally, an update to the drive sprocket housing is also being worked on to make the drive sprockets more easily replaceable. Another PIB will be issued when that design is complete and ready for production.

